


MAY 21 1971

Distribution:  
Docket   
BWR-1 File  
RSBoyd, DRL  
SMKari, DRL  
VBenaroya, DRL

Docket No. 50-263

Dr. Spencer H. Bush  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545


Dear Dr. Bush:

Three copies of the following are transmitted  
for the information of the Committee:

NORTHERN STATES POWER COMPANY  
(Monticello Nuclear Generating Unit No. 1)

1. NSP letter, dated May 12, 1971 reporting occurrence in which high flow sensors for main steam line B have been inoperable above 50% power level during startup testing.
2. NSP letter, dated May 18, 1971 reporting failure to start on 12 Diesel Generator during 100% power reactor testing.

Sincerely,



Peter A. Morris, Director  
Division of Reactor Licensing

Enclosures:  
As stated

(3)

OFFICE ▶	DRL:BWR-1 SMKari:ms	DRL:BWR-1	DRL:AD:BWR		
SURNAME ▶	x7791	DFK:ms	RSBoyd		
DATE ▶	5/21/71	5/21/71	5/21/71		

Form AEC-818 (Rev. 9-58)

U.S. GOVERNMENT PRINTING OFFICE: 1969-O-902,749

9211250301 710521  
PDR ADOCK 05000263  
PDR