

JUN 10 1985

Docket No. 50-123

University of Missouri-Rolla
ATTN: Dr. Don Warner, Dean
School of Mines and
Metallurgy
Rolla, MO 65401

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. K. R. Ridgway and E. R. Schweibinz of this office on May 21-22, 1985, of activities at the University of Missouri-Rolla authorized by NRC Operating License No. R-79 and to the discussion of our findings with Dr. Bolon and others of the staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations with NRC requirements were identified during the course of the inspection.

In accordance with the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original Signed by C.E. Norelius"

C. E. Norelius, Director
Division of Reactor Projects

Enclosure: Inspection Report
No. 50-123/85002(DRP)

cc w/enclosure:
Dr. A. Bolon
DMB/Document Control Desk (RIDS)

8507010177 850610
PDR ADOCK 05000123
G PDR

RIII
[Signature]
Ridgway/kja
06/10/85

RIII
[Signature]
Schweibinz
6-10-85

RIII
[Signature]
Norelius
Wio

1E01
||