

yellow

May 23, 1985

Alabama Power Company  
ATTN: Mr. R. P. McDonald  
Senior Vice President-Nuclear Generation  
P. O. Box 2641  
Birmingham, AL 35291

Gentlemen:

SUBJECT: REPORT NOS. 50-348/85-15 AND 50-364/85-15

On March 11 - 28, 1985, NRC inspected activities authorized by NRC License Nos. NPF-2 and NPF-8 for your Farley facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to unresolved items identified in the inspection report. These matters will be pursued during future inspections.

Should you have any questions concerning this letter, please contact us.

Sincerely,

(Original signed by DMVerrelli)

David M. Verrelli, Chief  
Reactor Projects Branch 1  
Division of Reactor Projects

Enclosure:  
Inspection Report Nos. 50-348/85-15  
and 50-364/85-15

cc w/encl:  
W. O. Whitt, Executive Vice President  
J. D. Woodard, Plant Manager  
W. G. Hairston, III, Manager, Nuclear Engineering  
and Technical Support  
J. W. McGowan, Manager-Safety Audit  
and Engineering Review  
H. O. Thrash, Manager, Nuclear Operations  
and Administration  
W. G. Ware, Supervisor-Safety Audit  
and Engineering Review

bcc w/encl: (See page 2)

8507010420 850523  
PDR ADDCK 05000348  
G PDR

11  
IEO1

Alabama Power Company

2

May 23, 1985

bcc w/encl:  
NRC Resident Inspector  
E. Reeves, Project Manager, NRR  
Document Control Desk  
State of Alabama

RII

*DF*  
DFalconer:sa  
05/20/85

RII

*SA*  
CJulian  
05/21/85

RII

*AG*  
AFGibson  
05/21/85

RII

*FC*  
FCantrell  
05/21/85