

ENCLOSURE 2

NOTICE OF DEVIATION

Duke Power Company
McGuire, Units 1 and 2

Docket Nos. 50-369 and 50-370
License Nos. NPF-9 and NPF-17
EA 84-135

The following deviations were identified during an inspection conducted on September 24-28, 1984.

1. Duke Power Company's letters of November 18, 1983 and February 20, 1984 to the NRC committed to provide battery-powered hand lanterns in the control room to be used in emergency situations by the plant operators.

Contrary to the above, at the beginning of this inspection, no battery-powered hand lanterns were provided in the control room.

2. Duke Power Company's letter of December 14, 1982 to the NRC committed to providing portable radios for communications between the Standby Shutdown Facility and the auxiliary feedwater local control stations.

Contrary to the above, at the beginning of this inspection, direct radio communication could not be established between the Standby Shutdown Facility and the auxiliary feedwater local control stations due to transmission interferences caused by plant structures. Therefore, the radios were nonfunctional.

Please provide in writing within 30 days of the date of this Notice a description of corrective actions taken regarding these deviations, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Date: MAR 15 1985

8507220328 850315
PDR ADOCK 05000369
Q PDR