Tom Barrakat Coleman Safety & Security Products, Inc 2820 Thatcher Road Downers Grove, Illinois 60515

Dear Mr. Barakat:

Based on the information and test data submitted in your application dated October 12, 1995, and subsequent letters, with enclosures thereto, we conclude that the Model 9.0 V and 120 V/AC Series smoke detectors are acceptable for licensing purposes in accordance with the conditions of the enclosed registration certificate (NR-0545-D-101-E). A copy of the certificate has been forwarded to the appropriate reviewer for licensing action.

Please be advised that you must manufacture and distribute the product in accordance with the statements and representations contained in your application, with enclosures thereto, and the information set out in your registration certificate. As a general rule, you must request and obtain an amendment to the certificate before you make changes or modifications to the information submitted to obtain the certificate.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions.

You are obligated to notify us promptly in writing should you decide to no longer manufacture or offer service support for the product.

Please be aware that, as a holder of an NRC registration, you may be subject to the NRC's licensing fees in accordance with 10 CFR Part 170, and annual fees in accordance with 10 CFR Part 171. If you have any questions concerning the fee requirements, please contact the License Fee and Debt Collection Branch at (301) 415-6096.

If you have any questions, please contact me at (301) 415-5787 or Mr. Douglas A. Broaddus at (301) 415-5847.

Sincerely,

Christopher Brown, General Engineer Sealed Source Safety Section Medical, Academic, and Commercial Use Safety Branch Division of Industrial and Medical Nuclear Safety Office of Nuclear Material Safety And Safeguards

Enclosure: As stated

cc w/encl: Skimberley, LFDCB

Distribution:

SSSS r/f SSD-95-101

NE01

SSD File # NR-0545-D-101-E

DOCUMENT NAME: C:\OFFICE\WPWIN\WPDOCS\SEATT.CMP

9701140026 961230 PDR RC \* SSD PDR FICIAL RECORD COPY