

OCT 22 1985

Docket No. 50-341

The Detroit Edison Company
ATTN: Wayne H. Jens
Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. Snell and others of this office on October 1-3, 1985, of activities at the Enrico Fermi Atomic Power Plant, Unit 2 authorized by NRC Operating License No. NPF-33 and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection. However, a weakness was identified which will need corrective action by your staff. This weakness is summarized in the attached Appendix to this letter. As required by 10 CFR Part 50, Appendix E, IV.F, any weaknesses that are identified must be corrected. Accordingly, you are requested to submit a written statement within 45 days of the date of this letter describing your planned actions for correcting the weakness identified in the Appendix.

The response directed by this letter is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

*JE 35
delete
RTII*

8510280352 851022
PDR ADOCK 05000341
PDR

11

The Detroit Edison Company

2 OCT 22 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosures:

- 1. Appendix, Exercise Weakness
- 2. Inspection Report No. 50-341/85041(DRSS)

cc w/enclosures:

- L. P. Bregni, Licensing Engineer
- P. A. Marquardt, Corporate Legal Department
- DCS/RSB (RIDS)
- Licensing Fee Management Branch
- Resident Inspector, RIII
- Ronald Callen, Michigan Public Service Commission
- Harry H. Voigt, Esq. Nuclear Facilities and Environmental Monitoring Section
- Monroe County Office of Civil Preparedness
- W. Weaver, FEMA, Region V
- D. Matthews, EPB, OIE

RIII
[Signature]
Shelton/mj
10/18/85

yes
RIII
NRW 10/21/85
Williamsen

RIII
[Signature]
Phillips
ya

RIII
[Signature]
Wright

RIII
[Signature]
Shafer

Appendix

EXERCISE WEAKNESS

Licensee personnel failed to incorporate current and forecast meteorology (primarily wind direction) into the protective action decisionmaking process which resulted in conveying marginally acceptable protective action recommendations to the State of Michigan. Open Item No. 341/85041-01 (Sections 4.a and 4.e).