VERMONT YANKEE NUCLEAR POWER CORPORATION



RD 5, Box 169, Ferry Road, Brattleboro, VT 05301

FVY 85-76

REPLYTO

ENGINEERING OFFICE

1671 WORCESTER ROAD FRAMINGHAM, MASSACHUSETTS 01701 TELEPHONE 617-872-8100

August 20, 1985

U.S. Nuclear Regulatory Commission Office of Inspection & Enforcement Region I 631 Park Avenue King of Prussia, PA 19406

Attention:

Thomas E. Murley

Regional Administrator

References:

a) License No. DPR-28 (Docket No. 50-271)

b) Letter, USNRC to VYNPC, Inspection 50-271/84-23,

dated 11/20/84

c) Letter, VYNPC to USNRC, Response to Inspection

Report 84-23

Dear Sir:

Subject:

Inspection Report 84-23

In our response to Inspection Report 84-23 [Reference c)], we stated our intention to have an improved shelf life controls program in place by September 14, 1985.

The purpose of this letter is to formally notify you of a recent modification to our schedule. As discussed with your staff, we will be unable to complete the improvements by September 14, 1985, due to the unanticipated scope of the effort. We now expect to implement the revised controls by December 31, 1985, however, we will continue the interim measures described in our May 31, 1985 letter [Reference c)] until that time.

Based on discussions with Mr. William Raymond of your staff, we understand that this extension is acceptable; however, should you have any questions, please contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Warren P. Murphy

Vice President and

Manager of Operations

/dm

8509090087 850820 PDR ADDCK 05000271 G PDR

1801 1/0