

# Leeco Diagnostics, Inc.

21705 EVERGREEN • P.O. BOX 5126 • SOUTHFIELD, MICH. 48075-5126

(313) 353-2620 • (800) 258-8933 • TWX 810-224-4687

30-14801

April 18, 1985

U.S. Nuclear Regulatory Commission  
Region III  
Materials Licensing Branch  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

To Whom It May Concern:


Following a recent review of contamination monitoring at our facility (NRC License #21-18294-02G), it was suggested by our consulting physicist that we change our action levels for decontamination. Following recommendations in the NRC Guide 8.23 "Radiation Safety Surveys At Medical Institutions", we have chosen action levels of 220 dpm/100 sq cm for unrestricted areas and 2200 dpm/100 sq cm for restricted areas. The restricted areas consist of sinks and hoods in the hot lab, QC lab, and glassware decon room; and special waste storage areas in the warehouse.

We feel that these new action levels more appropriately reflect the routinely achievable radiological contamination conditions at LEECO Diagnostics.

Please contact our health physics consultant, James Tomlinson, at (313)662-3197 if you have any questions concerning the new action levels.

Thank you for your consideration in this matter.

Sincerely,

  
John L. Watkins  
Radiation Safety Officer

LEEEO DIAGNOSTICS, INC.

JTW/cg

Approved	APR 23 1985
Check No.	2284
Amount	3.13
Type	and
Date Check Rec'd	8/1/85
Received By	

RECEIVED

APR 24 1985

REGION III

8509160143 850820  
REG3 LIC30  
21-18294-01 PDR

CONTROL NO. 78783

APR 24 1985