

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Shoreham Nuclear Power Station Unit #1										DOCKET NUMBER (2) 0 5 0 0 0 3 2 2				PAGE (3) 1 OF 2								
TITLE (4) Unprotected Vital Area																						
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)									
1	2	2	9	8	5	8	5	0	5	6	0	0	0	1	0	3	8	6	0 5 0 0 0			
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5 (Check one or more of the following) (11)																			
POWER LEVEL (10) 01010			20.402(b)				20.405(c)				80.73(a)(2)(iv)				73.71(b)							
			20.405(a)(1)(i)				80.36(a)(1)				80.73(a)(2)(v)				73.71(c)							
			20.405(a)(1)(ii)				80.36(a)(2)				80.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)							
			20.405(a)(1)(iii)				80.73(a)(2)(i)				80.73(a)(2)(vii)(A)											
			20.405(a)(1)(iv)				80.73(a)(2)(ii)				80.73(a)(2)(vii)(B)											
			20.405(a)(1)(v)				80.73(a)(2)(iii)				80.73(a)(2)(ix)											
LICENSEE CONTACT FOR THIS LER (12)																						
NAME Robert W. Grunseich, Operational Compliance Engineer										TELEPHONE NUMBER 5 1 6 9 2 9 - 8 3 0 0												
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																						
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC													
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR								
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO												
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)																						
<p>On Sunday, December 29, 1985 at 1144, a contract security force sergeant, while on a routine inspection of guard posts, found a security officer asleep at his assigned post. The security officer found asleep had been posted to control access to the Reactor Building refueling floor, elevation 175'5", a vital area. The plant was in Operational Condition 5 for an outage with the mode switch in shutdown and the Reactor vessel head removed. The last logged entry into the area was at 1005. The sergeant performed an immediate survey of the vital area to verify that no unauthorized personnel were present. Shortly thereafter, the security guard was relieved from the post and subsequently suspended from duty. The security sergeant notified the LILCO Shift Security Agent at approximately 1355, almost two hours after the event occurred. The Watch Engineer was notified at 1412 and the NRC was notified at 1437. The security sergeant involved was counselled as to the importance for timely notification of his supervisors and appropriate plant personnel. Disciplinary action for this individual is pending. The event was discussed with the contract security management and will be discussed with the entire contract security organization. In addition, the event, as it pertains to reporting requirements, will be addressed in future training.</p>																						
8601160338 860103 PDR ADDOCK 05000322 S PDR																						

LE22  
1/1

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO 3150-0104  
EXPIRES 8/31/85

FACILITY NAME (1):  Shoreham Nuclear Power Station Unit #1	DOCKET NUMBER (2):  05000322815-056-00002 OF 02	LER NUMBER (3):			PAGE (3):
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	

TEXT (If more space is required, use address: NRC Form 288A-2 (17))

On Sunday, December 29, 1985 at 1144, a contract security force sergeant, while on a routine inspection of guard posts, found a security officer asleep at his assigned post. The plant was in Operational Condition 5 during an outage, with the mode switch in shutdown and the Reactor vessel head removed.

The security sergeant woke the guard, and immediately performed a survey of the vital area to verify that no unauthorized personnel were present. Shortly thereafter, the guard was relieved from the post. A more intense search of the area was conducted and revealed no indications of intrusion or damage.

The security sergeant notified the LILCO Shift Security Agent at approximately 1355, over two hours after the event occurred. At 1412, the Watch Engineer was notified and the NRC was notified at 1437.

Although it is not known how long the guard had been asleep, the last logged entry into the area was at 1005.

Upon further investigation of the event, the guard found asleep was suspended from duty with further disciplinary action pending. The security sergeant was counselled as to the importance for timely notification to his supervisors and plant personnel. Disciplinary action for this individual is also pending.

The event and its ramifications have been discussed with the contract security force management and the seriousness and consequences of this event will be addressed to all members of the contract security force organization. In addition, the significance of this event, as it pertains to reporting requirements and the need for performing security duties at vital areas, will be addressed in future training.



## LONG ISLAND LIGHTING COMPANY

SHOREHAM NUCLEAR POWER STATION • P.O. BOX 628 • WADING RIVER, NEW YORK 11792

TEL. (516) 929-8300

January 3, 1986

PM 86-001


Mr. Richard Starostecki  
U.S. Nuclear Regulatory Commission  
Region One  
631 Park Avenue  
King of Prussia, Pa. 19406

Dear Sir:

In accordance with 10CFR73.71(c), enclosed is a copy of Shoreham Nuclear Power Station Unit 1's License Event Report 85-056.

It is requested that this letter be withheld from public disclosure pursuant to 10CFR73.21 in that it contains information concerning this licensee's physical protection program.

Sincerely yours,

  
W. E. Steiger  
Plant Manager

WES/gr

Enclosure

cc: Director, Inspection and Enforcement, USNRC  
John Berry, Senior Resident Inspector  
Institute of Nuclear Power Operations, Records Center  
American Nuclear Insurers

SR. AE1.0200

RECEIVED-NI-SION 1  
1986 JAN -6 PM 1:50