

JAN 14 1986

Docket/License: 50-213/DPR-61

Connecticut Yankee Atomic Power Company
ATTN: Mr. J. F. Opeka
Senior Vice President - Nuclear
Engineering and Operations
P. O. Box 270
Hartford, Connecticut 06101

Gentlemen:

Subject: Resident Inspection 50-213/85-21 (10/16/85-12/02/85)

This transmits the findings of the routine NRC inspection of the Haddam Neck Plant on October 16 - December 2, 1985. These findings have been discussed with Mr. R. Graves of your staff.

This inspection cited, as a violation, multiple instances of failure to conform to the requirements of your administrative control procedures. While these specific failures did not result in any actual adverse plant operating conditions, we are concerned that they may be indicative of a lack of concern for procedure adherence on the part of the facility staff. Therefore, in addition to your reply to the individual violations, please include your evaluation of the effectiveness of your quality assurance program in assuring conformance with its implementing procedures and describe your plans for improving that conformance overall. Also, in regard to Violation Citation 1.f, please address the failure to change surveillance procedures as necessitated by design changes as that relates to the effectiveness of your corrective actions on the reactor cavity seal failure and the associated December 1984 NRC Order.

The second violation cited was for failure to adequately correct a problem with overdue procedure reviews. This item is worth particular note because it is for inadequate correction of an identified problem.

We also wish to call Report Detail 6.4 to your attention. This item deals with apparent interaction between steam flow measurement channels. Although the corrective action described does address the problem symptom, we did not find that the root cause and its implications have been identified.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:

8601230285 860114
PDR ADOCK 05000213
G PDR

Edward C. Wenzinger, Chief
Projects Branch No. 3
Division of Reactor Projects

11
IEO1

JAN * 4 1986

Connecticut Yankee Atomic Power Company 2

Enclosures:

1. Appendix A, Notice of Violations
2. NRC Region I Report 50-213/85-21

cc w/encls:

R. Graves, Plant Superintendent
D. O. Nordquist, Manager of Quality Assurance
R. T. Laudenat, Manager, Generation Facilities Licensing
E. J. Mroczka, Vice President, Nuclear Operations
Gerald Garfield, Esquire
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of Connecticut

bcc w/encls:

Region I Docket Room
DRP Section Chief
M. McBride, RI, Pilgrim
J. Shedlosky, SRI, Millstone 1 & 2
T. Rebelowski, SRI, Millstone 3
F. Akstulewicz, LPM, NRR
J. Durr, RI (esp. Detail 4.1)
C. Anderson, RI (esp. Detail 4.5)
J. Wiggins, RI (esp. Detail 4.1)
M. Shanbaky, RI (esp. Detail 6.3)

DRP:RI

RJD for
Swetland/meo

1/7/86

1/10/86

DRP:RI

RJD for
McCabe

1/10/86

DRP:RI

[Signature]
Wenzinger

1/14/86

OFFICIAL RECORD COPY