Docket No. 50-315 Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine Material Control and Accounting inspection conducted by Mr. T. J. Madeda of this office on November 18-21, 1985, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. Smith, Jr., and other members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

Areas examined during the inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection will not be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. L. Axelson, Chief Nuclear Materials Safety and Safeguards Branch

Enclosure: Inspection Report No. 50-315/85039(DRSS) No. 50-316/85039(DRSS) (PART 2.790(d) INFORMATION)

See Attached Distribution

8512120368 851206 PDR ADOCK 05000315 PDR IE02

· Distribution

cc w/enclosure: W. G. Smith, Jr., Plant Manager

cc w/enclosure, w/o
 (PART 2.790(d) INFORMATION)
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

Manda/kja Pizv05/85 RIII

Suermann Leu Axelson 12/4/81