

Roseland Community Hospital Association

45 WEST 111TH STREET . CHICAGO, ILLINOIS 60628

January 14, 1986

D.J. Sreniawski, Chief Nuclear Materials Safety Section 2 U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60136

RE: License No. 12-10943-02 Inspection

Dear Mr. Sreniawski:

This is in reply to your letter of December 12, 1985 regarding the above referenced inspection, as follows:

 The leak tests referenced in Item 1 had been performed and copies of the certificates are enclosed. It is unfortunate the inspection took place on a day when our Chief Nuclear Technologist was alone and busy.

Therefore, we were actually not in non-compliance on this item.

Regarding Item 2 in your letter, it is true that one weekly area survey was apparently not performed or recorded during the week of September 14, 1985. Our Chief Nuclear Tech advised us he had instructed the back-up technician on how to perform and record surveys, but the task was not done. Our corrective action will be to obtain a more dependable back-up technician for our Chief Nuclear Technologist when he is on vacation or off-duty. The particular back-up technician is no longer with our hospital, for other reasons beyond those listed in this letter.

We trust the enclosures, explanations, and corrective actions will be deemed satisfactory.

Sincerely,

Arthur Isherwood

President

8602040145 860129

MEGG LICGO

PDR

AI:ec encl.

cc: Mr. James Patterson

"Serving the Community Since 1924"

JAN 2 1 1986

STAN A. HUBER CONSULTANTS, INC.

-- 200 N. CEDAR ROAD -- NEW LENOX IL 60451 -- PHONE (815) 485-6161 --

SEALED GAMMA/BETA SOURCE - LEAK TEST CERTIFICATE

LEAK TEST REPORT DATE:

08-07-85

FACILITY:

ROSELAND COMMUNITY HOSPITAL

IL

FACILITY RADIOACTIVE MATERIALS LICENSE NO.: 12-10943-02

V NRC

__ STATE

SOURCE IDENTIFICATION

RADIONUCLIDE:

CS-137

ACTIVITY: .218 MCI

CALIBRATION DATE:

03-10-78

MANUFACTURER: NEN

MODEL NO. :

NES-356

SERIAL NO.: 319-187-14

ASSAY RESULTS:

GROSS COUNTS/MIN NET COUNTS/MIN

UCI

WET WIPE

122

<9.1E-07

DRY WIPE

103

0

<9.1E-87

BACKGROUND & TIME OF ASSAY 133 CPM

ANALYSIS OF RESULTS:

SOURCE IS NOT LEAKING AT THIS TIME. REMOVABLE CONTAMINATION IS LESS THAN 5 X 10E-3 UCI.

NEXT LEAK TEST DUE:

JANUARY 1986

LEAK TEST PERFORMED BY:

MARK J. KAPELINSKI

DATE:

07-31-85

ANALYSIS PERFORMED BY:

STAN A. HUBER SH

DATE: 08-06-85

JAN 0.1 1986

STANT A. HUBER CONSULTA ITS. INC.

-- 285 ESSEY LANE -- NEW LENGY IL 60451 -- PHONE -815: 722-8000 --

SEALED GAMMA/BETA SOURCE - LEAK TEST CERTIFICATE

LEAK TEST REPORT DATE:

2-11-85

FACILITY:

ROSELAND COMMUNITY HOSPITAL

CHICAGO IL

FACILITY RADIOACTIVE MATERIALS LICENSE NO.: 12-10943-02

NRC __ STATE

SOURCE IDENTIFICATION

ACTIVITY: .218 MCI

RADIONUCLIDE: CS-137 CALIBRATION DATE: 3-10-78

MANUFACTURER: NEW

MODEL NO.: NES-356

SERIAL NO.: 319-187-14

HSSAY RESULTS:

	GROSS COUNTS/MIN	MET COUNTS/MIN	UC1
WET WIPE	100	2	1.82E-06
DRY WIPE	126	28	2.548E-05

BACKGROUND & TIME OF ASSAY 98 CPM

ANALYSIS OF RESULTS:

SOURCE IS NOT LEAKING AT THIS TIME.

REMOVABLE CONTAMINATION IS LESS THAN 5 X 10E-3 UCI.

NEXT LEAK TEST DUE: JULY 1985

LEAK TEST PERFORMED BY: JOHN J. HOLLINDEN

DATE: 1-23-85

ANALYSIS PERFORMED BY: STAN A. HUBER OF

DATE: 2-11-85

STAN A. HUBER CONSULTANTS, INC.

-- 235 ESSEX LANE -- NEW LENDX 1L 80451 -- PHONE (815) 722-8009 --

SEALED GAMMA/BETA SOURCE - LEAK TEST CERTIFICATE

LEAK TEST REPORT DATE:

8-8-84

FACILITY:

ROSELAND HOSPITAL

CHICAGO

IL

FACILITY RADIOACTIVE MATERIALS LICENSE NO.: 12-18943-82

✓ NRC __ STATE

SOURCE IDENTIFICATION

RADIONUCLIDE: CS-137 ACTIVITY: .218 MCI
CALIBRATION DATE: 3-10-78 MANUFACTURER: NEN
MODEL NO.: NES-356 SERIAL NO.: 319-187-1

SERIAL NO.: 319-187-14

ASSAY RESULTS:

GROSS COUNTS/MIN NET COUNTS/MIN UCI

WET WIPE 94

0

<9.1E-07 ∠9.1E-87

DRY WIPE 109

BACKGROUND & TIME OF ASSAY 115 CPM

ANALYSIS OF RESULTS:

SOURCE IS NOT LEAKING AT THIS TIME.

REMOVABLE CONTAMINATION IS LESS THAN 5 X 10E-3 UCI.

NEXT LEAK TEST DUE: JANUARY 1985

LEAK TEST PERFORMED BY: JOHN J. HOLLINDEN

DATE: 7-18-84

ANALYSIS PERFORMED BY: STAN A. HUBER J.J. H

DATE:

8-7-84

STAN A. HUBER CONSULTANTS, INC.

-- 235 ESSEX LANE -- NEW LENOX IL 60451 -- PHONE (815) 722-8009 --

SEALED GAMMA/BETA SOURCE - LEAK TEST CERTIFICATE ______

LEAK TEST REPORT DATE:

2/13/84

FACILITY:

ROSELAND HOSPITAL

CHICAGO

ILLINOIS

FACILITY RADIOACTIVE MATERIALS LICENSE NO.: 12-10943-02

X NRC STATE

SOURCE IDENTIFICATION

RADIONUCLIDE: CS-137 ACTIVITY: .218 MCI

CALIBRATION DATE: 3/10/78

MANUFACTURER: NEN

MODEL NO.:

NES 356

SERIAL NO.: 319 187 14

ASSAY RESULTS:

	GROSS	COUNTS/MIN	NET COUNTS/MIN	UCI
WET WIPE		150	0	∠9.1E-07
DRY WIPE		159	5	4.55E-06

BACKGROUND @ TIME OF ASSAY 154 CPM

ANALYSIS OF RESULTS:

SOURCE IS NOT LEAKING AT THIS TIME. REMOVABLE CONTAMINATION IS LESS THAN 5 X 10E-3 UCI.

NEXT LEAK TEST DUE: JULY 1984

LEAK TEST PERFORMED BY: JATIN PANDYA

DATE: 2/1/84


ANALYSIS PERFORMED BY: STAN A. HUBER 48

DATE:

2/13/84

SEALED GAMMA/ BETA SOURCE - LEAK TEST CERTIFICATE

Leak Test Report Date Facility: ROSELAN			City: C	HI CAGO	State: 1L
Facility Radioactive	Material Lic	ense No: _	12-1094	3-02	_
⊠ NR	c [STATE			
Source Identificatio	n				
Radionuclide: _	CS-137		Activity:	.218	mCi
Calibration Dat	e: 83/1	8/78	Manufacturer	NEN	
Model No.: N	ES 356		Serial No:	319-187-14	
Assay Results:		ROSS COUNTS		COUNTS/MIN	uCi
	WET WIPE	82 123		0	∠9.1E-07 1.801E-05
	DRY WIPE	120			
Analysis of Results:	Source Is r	not leaking	at this time. less than 5 x 3	.7	
,					
NEXT LEAK TEST DUE:	01/	84			
Leak Test Performed	by: STA	N BUHR		Date: _	07/29/83
Analysis Performed b	y: STA	AN BUHR 544	4	Date:	08/01/83



SEALED GAMMA/ BETA SOURCE - LEAK TEST CERTIFICATE

Leak Test Report Facility:POSFLA	AND COMM HOSP	-83	City: CHICAGO		State: IL
Facility Radioact					State: It
	ave nacerial b.	rcense No:	12-10943-02		
	NRC	☐ STATE			
Source Identifica	tion				
Radionuclide	:CS137	Ac	ctivity: .218		mCi
Calibration	Date: 3-10	-78 . Ma	anufacturer: N	EN .	
Model No.: N	NES-356	Se	erial No: 319-1	87-14	
ssay Results:		GROSS COUNTS/M	IN NET COUNTS	/MIN	uCi
	WET WIPE	3	0		<9.1E-07
	DRY WIPE		4		₹9.18-07
nalysis of Result	Background	not looking at	у6		(7.12-07
nalysis of Result	Background	not looking at	y6		(7.12-07
nalysis of Result	Source Is Removable	not leaking at t	y6		(7.12-07
	Source is Removable JUL	not leaking at t	y6		1-26-83

