MEMORANDUM TO:

Herbert N. Berkow, Director

Project Directorate II-2

Division of Reactor Projects - I/II, NRR

FROM:

Victor Nerses, Senior Project Manager ORIGINAL SIGNED BY:

Project Directorate II-2

Division of Reactor Projects - I/II, NRR

SUBJECT:

FORTHCOMING MEETING WITH DUKE POWER COMPANY

(TAC NOS. M97264 AND M97265)

DATE & TIME:

Wednesday, July 9, 1997

8:30 a.m.

LOCATION:

McGuire Nuclear Station

Building 7438

12700 Hagers Ferry Road Huntersville, North Carolina

PURPOSE:

To discuss the licensee's revisions to the 1996 McGuire Updated Final Safety Analysis Report (UFSAR) and how the

1996 revision complies with 10 CFR 50.71.

PARTICIPANTS*:

NRC

Duke Power Company

Victor Nerses, NRR

victor nerses, NK

Mike Cash, et al.

et al.

Docket Nos. 50-369 and 50-370

Attachment: Review Items on UFSAR

DISTRIBUTION see next page

cc w/att: See next page

Contact: Victor Nerses, NRR

415-1484

*Meetings between NRC technical staff and applicants or licensees are open for interested members of the public, petitioners, intervenors, or other parties to attend as observers pursuant to "Commission Policy Statement on Staff Meetings Open to the Public," 59 Federal Register 48344, 9/20/94. Persons who wish to observe should contact the project manager at 301-415-1484 within 24 hours before the meeting.

DOCUMENT NAME: G:\MCGUIRE\MCG97624.NTC

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	PDII-3/PM	PDII-4/LA	PD1/1-2/D
NAME	VNerses cn	LBerry (1)	HBerckow /
DATE	06/20/97	06/9/97	06/20/97

OFFICIAL RECORD COPY

NRC FILE CENTER COPY

9706230377 970620 PDR ADOCK 05000369 11



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

June 20, 1997

MEMORANDUM TO:

Herbert N. Berkow, Director

Project Directorate II-2

Division of Reactor Projects - I/II, NRR

FROM:

Victor Nerses, Senior Project Manager

Project Directorate II-2

Division of Reactor Projects - I/II, NRR

SUBJECT:

FORTHCOMING MEETING WITH DUKE POWER COMPANY

(TAC NOS. M97264 AND M97265)

DATE & TIME:

Wednesday, July 9, 1997

8:30 a.m.

LOCATION:

McGuire Nuclear Station

Building 7438

12700 Hagers Ferry Road

Huntersville, North Carolina

PURPOSE:

To discuss the licensee's revisions to the 1996 McGuire

Updated Final Safety Analysis Report (UFSAR) and how the

1996 revision complies with 10 CFR 50.71.

PARTICIPANTS*:

NRC

Duke Power Company

Victor Nerses, NRR

et al.

Mike Cash, et al.

Docket Nos. 50-369 and 50-370

Attachment: Review Items on UFSAR

cc w/att: See next page

Contact: Victor Nerses, NRR

415-1484

*Meetings between NRC technical staff and applicants or licensees are open for interested members of the public, petitioners, intervenors, or other parties to attend as observers pursuant to "Commission Policy Statement on Staff Meetings Open to the Public," 59 Federal Register 48344, 9/20/94. Persons who wish to observe should contact the project manager at 301-415-1484 within 24 hours before the meeting.

E-Mail

S. Collins/F. Miraglia
R. Zimmerman (RPZ)
B. Boger (BAB2)
J. Zwolinski (JAZ)
H. Berkow (HNB)
V. Nerses (VXN)
L. Berry (LGB)
D. Ross (SAM)
OPA (e-mail to OPA)
J. Johnson, RII
C. Casto, RII
G. Tracy, EDO (GMT)
K. Clark, PAO (KMC2)
PMNS (Meeting Announcement Coordinator)

Hard Copy

Docket File PUBLIC PD II-2 Reading OGC ACRS

cc: Licensee & Service List

1996 UPDATED FSAR

AGENDA ITEMS TO BE DISCUSSED WITH LICENSEE

(TAC NOS. M97264 AND M97265)

NOTE: The majority of the items listed below deal with the reason for the change and the majority of them can be answered by simply referencing an NRC approval document, a McGuire annual 10 CFR 50.59 report or an NRC generic guidance document. RFC = reason for change.

Section 1.4, RFC

Section 1.8.25.4, pg. 1-38, RFC Section 1.8.26, pg. 1-40, RFC

Table 1-5 - bottom right hand corner has no effective dates printed, other apparent errors

Table 1-6 - pg. 21 of 69, RFC

Section 2.3.3, pg. 2-2, RFC

Section 2.5.5.2, pg. 2-60, RFC

Section 3.4, pg. 3-43, sentence does not read correctly

Section 3.6.2.2.1, pg. 3-65, RFC

Section 3.7.1.3, pg. 3-80, RFC

Section 3.7.2.1.3, pg. 3-94, RFC

Table 3-20, pg. 5 of 7, Duke Pipe Rupture Criteria, added words about GL 87-11 not requiring arbitrary intermediate breaks to be postulated, RFC

Table 3-20, pg. 6 of 7, RFC

Chapter 4 - List of Figures: added; deleted one figure, but not apparent what the change was in 4--30 and 4--34

Section 4.2.1.1.1.3, pg. 4-9, RFC

Section 4.2.1.2.2, pg. 4-11 and 4-12, RFC

Section 4.2.1.3.1.1, pg. 4-13, 4-14, 4-15, 4-16, RFC

Section 4.2.3.2.1, pg. 4-31, 4-32, 4-33, RFC (why is there a "5" in the margin?)

Section 4.2.3.3.2, 4-43, RFC

4.3.2.2.7, 4-62 (0), 4-64(N), RFC

4.3.2.6, pg. 4-73, 4-74, 4-75, 4-76, 4-77, RFC

4.3.2.7.5, pg. 4-79, RFC

4.3.5, pg. 4-85, RFC

Table 4-1, pg. 3 of 4, RFC

Table 4-1, pg. 4 of 4, RFC

Table 4-4 (pg. 1 of 4), RFC

Table 4-4 (pg. 2 of 4), RFC

Table 4-4 (pg. 3 of 4), the May 14, 1996, revision shows a change but no "5" in margin of change.

Table 4-5 (pg. 1 of 2), RFC

Table 4-6, RFC

Table 4-7, pg. 1 of 2 and 2 of 2, RFC

Table 4-8, deleted, RFC

Table 4-9, pg. 1 of 2 and 2 of 2, deleted in its entirety, RFC

Table 4-10, deleted in its entirety, RFC

Table 4-11, deleted in its entirety, RFC

Table 4-13, was not deleted and it is shared on a page with Table 4-12 in the May 14, 1996, revision, but also Table 4-13 is shared on a page with Table 4-14 in the May 1, 1992, revision. It looks like there was a mistake made.

Table 4-22 is a new table. No comparable one on the September 1, 1993, page, RFC

Figure 4-22, deleted, RFC

Figure 4-30, the "5" on the May 14, 1996, page is in the wrong location

Figure 4-34, the Figure has been rearranged and it has been added to, RFC

Figure 4-51, not apparent to where the change between the May 14, 1996, revision and the May 1, 1992, revision

Figure 4-89, Is this a new figure?, RFC

5.2.2.3, pg. 5-30, RFC

5.5.13.2, pg. 5-99, RFC

5.5.13.3, pg. 5-100, RFC

Table 5-10, RFC

Table 5-31 (all 16 pages deleted), RFC

Chapter 6, List of Figures pg. viii, has "5" but appears no change took place for 6-110, 6-176, 177, and 190?

Steam Generator, pg. 6-29, sentence does not make sense without some punctuation

6.2.1.6.2, pg. 6-45, 6-46, RFC

Table 6-49, May 14, 1996, page had no "5" marked anywhere on the page. Why did this need to replace May 1, 1992, page in FSAR?

Table 6-50, same question as for Table 6-49

Table 6-51 to 6-63, same question as Table 6-49

Table 6-64, the May 1, 1992, page has Tables 6-63 and 6-64 on same page. However, the May 14, 1996, page only has Table 6-63 - what happened to Table 6-64?

Table 6-110, missing from FSAR pages 1-5 of May 1, 1992. The May 14, 1996, update only includes a change to pg. 4 of 5. Since May 1, 1992, revision pages are not available, cannot make any updates. Reason for missing page.

Table 6-125, 1 of 2, not apparent the nature of change

7.6.4, pg. 7-89, editorial, it still has an error

7.6.8.1.3.1, pg. 7-100, sections rewritten, why?

7.6.8.1.3.2, pg. 7-101, sections rewritten, why?

7.6.8.1.4, pg. 7-101, sections rewritten, why?

7.6.11.1.9.2, pg. 7-111, in the May 14, 1996, version, the sentence begins with "this is a summary flow diagram." What is "this" referring to?

7.6.15.1.1, pg. 7-118, added paragraph, why?

7.7.1.1.2, pg. 7-138, whole paragraphs deleted, why?

7.7.1.13.2, pg. 7-141, sentences changed. RFC (Also, error in the May 14, 1996, revision - the word "fines" should be "fires."

7.7.1.14.1, pg. 7-143, sentences changed. RFC

7.7.1.15, pg. 7-143, RFC

7.7.2.4, pg. 7-149, whole paragraph deleted. RFC

Table 7-14 (pg. 7 of 9), why the change in item 1? Range from 50 to 800 gpm to 0 to 600 gpm? (was a 50.59 done?)

Table 7-15 (pg. 1 of 3), why the change (was a 50.59 done?) (pg. 2 of 3 and 3 of 3), why the deletions (was a 50.59 done?)

Figures 7-10 and 7-11, why deleted?

Figure 7-19, RFC

Figure 7-28, RFC

Table 8-11, RFC

Table 8-12, RFC

Table 8-13, pg. 1 and 2 of 2, RFC

Figure 8-24, RFC

Figure 8-25, RFC

Figure 8-37, RFC

Figure 8-38, RFC

Figure 8-39, RFC

Fg. 9-3 and 9-4, RFC

Pg. 9-8, RFC

Pg. 9-9, RFC

Pg. 9-10, RFC

Pg. 9-12, 13, 14, RFC

Pg. 9-16, RFC

Pg. 9-19, RFC

Pgs. 9-20, 21, 22, RFC

Pgs. 9-24, 25, 26, 27, 28, RFC

Pgs. 9-29, 30, 31, 32, 33, RFC

Pgs. 9-38, 39, 41, 43, 44, 45, 46, 47, RFC

Pgs. 9-55, 56, 57, 59, 60, 62, 69, 70, RFC

Table 9-1, pg. 2 and 3 of 3, RFC

Table 9-3, 9-4, 9-5, 9-6, RFC

Table 9-8, pg. 1 and 2 of 2, RFC

Tables 9-14,15,16,17,18,19 (Note that Table 9-16 of May 1, 1992, revision was changed by Table 9-16 of May 14, but no "5" in margin of May 14, 1996, Table 9-16)

Table 9-28, 2, 3 and 4 of 4, RFC

Figures 9-8, 9-39, 40, 41, RFC

Figures 9-58, 59, 60, 61, 62, 63, 64, RFC

Figure 9-93, RFC

Pg. 10-8, RFC

Figures 10-30, 31, 32, 33, 34, RFC

Pgs. 11-43, 47, 51, 53, 54, RFC

Table 11-22, the May 14, 1996, page for this table shows revision (note the "5"'s) however, the May 1, 1992, page shows exactly the same thing (i.e., there is no change). So why was "5" put in the margin of the May 14, 1996 revision?

Table 11-27, pg. 1 and 2, RFC

Table 11-28, licensee notes changes on page 1 and 2 of 4 (May 1992) but page 3 of May 1992 has changes that are also on page 2 of May 1996

Figure 11-24 and 25, deleted, RFC

13.4.2.1, page 13-18, 13-19, RFC

15.1.5.2, pg. 15-27, RFC

15.2.6.2, pg. 15-39, RFC

15.2.8.2, pg. 15-44 and 45, RFC

15.4.1.2, pg. 15-60, RFC

15.4.2.2, pg. 15-62, RFC

15.4.3.4, pg. 15-70, RFC

15.4.8.3, pg. 15-85, RFC

15.6.5.2, pgs. 15-102, 103, 105, 106, 107, 109, 110, 111, 112, 114, 115, RFC

McGuire Nuclear Station Units 1 and 2

cc: Mr. Paul R. Newton Duke Power Company, PB05E 422 South Church Street Charlotte, North Carolina 28242-0001

County Manager of Mecklenberg County 720 East Fourth Street Charlotte, North Carolina 28202

Mr. Michael T. Cash
Regulatory Compliance Manager
McGuire Nuclear Station
Duke Power Company
12700 Hagers Ferry Road
Huntersville, North Carolina 280788985

J. Michael McGarry, III, Esquire Winston and Strawn 1400 L Street, NW. Washington, DC 20005

Senior Resident Inspector c/o U. S. Nuclear Regulatory Commission 12700 Hagers Ferry Road Huntersville, North Carolina 28078

Mr. T. Richard Puryear Owner's Group (NCEMC) Duke Power Company 4800 Concord Road York, South Carolina 29745

Dr. John M. Barry
Mecklenberg County
Department of Environmental
Protection
700 N. Tryon Street
Charlotte, North Carolina 28202

Mr. Dayne H. Brown, Director
Department of Environmental,
Health and Natural Resources
Division of Radiation Protection
P. O. Box 27687
Raleigh, North Carolina 27611-7687

Ms. Karen E. Long Assistant Attorney General North Carolina Department of Justice P. O. Box 629 Raleigh, North Carolina 27602

Mr. G. A. Copp Licensing - ECO50 Duke Power Company 526 South Church Street Charlotte, North Carolina 28242-0001

Regional Administrator, Region II U.S. Nuclear Regulatory Commission Atlanta Federal Center 61 Forsyth Street, S.W., Suite 23T85 Atlanta, Georgia 30303

Elaine Wathen, Lead REP Planner Division of Emergency Management 116 West Jones Street Raleigh, North Carolina 27603-1335

Mr. H. B. Barron Vice President, McGuire Site Duke Power Company 12700 Hagers Ferry Road Huntersville, North Carolina 28078