

JAN 02 1986

DMB COPY

Nanda Khedkar, M.D.
Stonebridge Professional Building
17577 South Kedzie
Suite 110
Hazelcrest, IL 60429

License No. 12-20287-01

30-18202

Dear Dr. Khedkar:

This refers to the routine safety inspection conducted by James R. Mullauer of this office on December 4 and 26, 1985, of activities authorized by NRC Byproduct Material License No. 12-20287-01 and to the discussion of our findings with you at the conclusion of the onsite inspection on December 4, 1985.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The violation noted is a repeat item. In your response to this violation, please describe why your proposed corrective action is expected to be more successful in preventing future or similar violations than the corrective action specified in your May 10, 1983 letter.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief
Nuclear Materials Safety
Section 2

Enclosure: Notice of Violation

cc w/enclosure:
DCS/RSB (RIDS)

RIII
Mullauer/ld
12-31-85

Yes
1/2/86
RIII
Sreniawski

B601100086 B60102
REG3 LIC30
12-20287-01 PDR

IE07
||