January 23, 1997

Mr. D. R. Gipson Senior Vice President Nuclear Generation The Detroit Edison Company 6400 North Dixie Highway Newport, MI 48166

SUBJECT: NRC INSPECTION REPORT NO. 50-341/96012(DRS)

Dear Mr. Gipson:

This refers to the inspection conducted by Mr. J. H. Neisler of this office on October 7-10, 28-31, November 4-7, 18-21, and December 12, 1996, at your Fermi 2 nuclear facility. At the conclusion of the inspection, the inspection results were discussed with those members of your staff identified in the enclosed report.

The inspection examined your activities relative to the rebuild of the main turbine, refurbishment of the Station Blackout/Appendix R combustion turbine, materials engineering relative to equivalent parts evaluations and your activities to correct main steam line vibration problems.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection. Your cooperation with us is appreciated.

Sincerely,

/s/ M. Leach (for)

Geoffrey E. Grant, Director Division of Reactor Safety

Docket No. 50-341

Enclosure: Inspection Report No. 50-341/96012(DRS)

<u>Distribution</u>: See attached list

SEE ATTACHED CONCURRENCES

DOCUMENT NAME: G:\FER96012.DRS

To receive a copy of this document, indicate in the box "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

N	RIII:DRS	DRP	RIII:	DRS	RIII:	:DRS	RIII	OFFICE
HAL	Leach/Grantos	ardner Jordan		Gardn	ler	Neis	NAME	
	01/23/97	/97	01/	/97	01/	/97	01/	DATE
_	01/23/97	/97	01/	/97	01/	/97	01/	DATE

OFFICIAL RECORD COPY

Mr. D. R. Gipson Senior Vice President Nuclear Generation The Detroit Edison Company 6400 North Dixie Highway Newport, MI 48166

SUBJECT: NRC INSPECTION REPORT NO. 50-341/96012(DRS)

Dear Mr. Gipson:

This refers to the inspection conducted by Mr. J. H. Neisler of this officer on October 7-10, 28-31, and November 4-7, 18-21, 1996, at your Fermi 2 nuclear facility. At the conclusion of the inspection, the inspection results were discussed with those members of your staff identified in the enclosed report.

The inspection examined your activities relative to the rebuild of the main turbine, refurbishment of the Station Blackout/Appendix R combustion turbine, materials, engineering relative to equivalent parts evaluations and your activities to correct main steam line vibration problems.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection. Your cooperation with us is appreciated.

Sincerely,

Geoffrey E. Grant, Director Division of Reactor Safety

Docket No. 50-341

Enclosure: Inspection Report No. 50-341/96012(DRS)

<u>Distribution:</u>
See attached list

DOCUMENT NAME: G:\FER96012.DRS

To receive a copy of this document, indicate in the box "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

OFFICE	RIII:DRS E	RIII:DRS L	RIII:DRP	RIII:DRS
NAME	Neisler Am	Gardner W	Jordan ARA-jar	Leach/Grant
DATE	01/22/97	01/22/97	01/23 /97	01/ /97

cc w/encls: N. Peterson, Supervisor of Compliance

P. A. Marquardt, Corporate Lega! Department

James R. Padgett, Michigan Public

Service Commission

Michigan Department of Public Health

Monroe County, Emergency Management Division

Distribution:

Docket File w/encl

PUBLIC IE-01 w/encl

OC/LFDCB w/encl

DRP w/encl DRS w/encl RIII PRR w/encl

SRI, Fermi w/encl

LPM, NRR w/encl

A. B. Beach, RIII w/encl W. L. Axelson, RIII w/encl Enf. Coordinator, RIII w/encl

CAA1 w/encl