



UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

OCT 2 1978

Report No.: 50-297/78-3

Docket No.: 50-297

License No.: R-120

Category: F

Licensee: North Carolina State University
Nuclear Engineering Department
Raleigh, North Carolina 27067

Facility Name: North Carolina State University (NCSU) PULSTAR Reactor

Inspection at: North Carolina State University at Raleigh

Inspection conducted: August 17, 1978

Inspector: R. J. Hennessey, Jr.

Reviewed by: SD Gillespie
F. P. Gillespie, Chief
Security and Investigation Section
Safeguards Branch

10/2/78
Date

Inspection Summary

Inspection of August 17, 1978 (Report No. 50-297/78-3)

Areas Inspected: Unannounced inspection of Physical Security Program as described by the licensee's Physical Security Plan. The inspection involved 7 inspector-hours by one NRC inspector, and was initiated during the licensee's regular working hours.

Results: No items of noncompliance were identified during the inspection.

S-E2 78 - 119
Copy 3 of 3 Pages
This Document is not to be
reproduced without specific
approval of IE:II

MATERIAL TRANSMITTED HEREWITH
CONTAINS 2760 INFORMATION

7810160099