
PTL-INSPECTOR NATIONWIDE AND INTERNATIONAL SERVICES





EXECUTIVE OFFICES

CERTIFIED MAIL RETURN RECEIPT REQUESTED

May 8, 1987

Mr. Thomas K. Thompson U.S. Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, PA 19406

Reference: License No. 37-00276-25

Control No. 105252

Dear Mr. Thompson:

This is in response to your letter dated April 14, 1987, regarding the two (2) open items that need clarification to renew our license.

We have revised Part A for item number 1 and Part D for item number 2. Attached you will find the revision to our Radiation Safety Program to insert into your manuals. We are enclosing two (2) copies.

We trust that the attached will comply to the additional information required.

Please note that when the name Pittsburgh Testing Laboratory or PTL is shown in our procedures, these refer to PTL-Inspectorate Inc. or PTL-II's. Subsequent procedures will reflect this change in name structure.

Should you have any questions, please feel free to contact me.

Very truly yours,

Kingsley D. Drake, P.E.

Liaison Officer

ELA/KDD/dw

8801250578 870807 REG1 LIC30 37-00276-25 PD

Enclosures

cc: Radiation Records

PDR

12 MAY 1987