

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Joseph M. Farley - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8	PAGE (3) 1 OF 0 1
---	---	-----------------------------

TITLE (4)
Special Report: Fire Door 453 Inoperable For More Than Seven Days

EVENT DATE (5)				LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)
02	26	88	88	005	00	03	21	88	J. M. Farley - Unit 2			0 5 0 0 0
												0 5 0 0 J

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)									
POWER LEVEL (10) 1 0 0	20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)						
	20.405(a)(1)(ii)	50.36(a)(1)	50.73(a)(2)(v)	73.71(e)						
	20.405(a)(1)(iii)	50.36(c)(2)	50.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 368A)						
	20.405(a)(1)(iv)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	Special Report per Tech. Spec. 3.7.12						
	20.405(a)(1)(v)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)							
20.405(a)(1)(vi)	50.73(a)(2)(iii)	50.73(a)(2)(x)								

LICENSEE CONTACT FOR THIS LER (12)

NAME J. D. Woodard, General Manager-Nuclear Plant	TELEPHONE NUMBER
	AREA CODE 2 0 5 8 9 9 - 5 1 5 6

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	

SUPPLEMENTAL REPORT EXPECTED (14)	EXPECTED SUBMISSION DATE (15)	MONTH DAY YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 0500 on 2-19-88, fire door 453 was declared inoperable because the latching device was broken. The door could not be repaired within seven days. Technical Specification 3.7.12 requires the fire door to be returned to operable status within seven days or a Special Report must be submitted within the following 30 days. Therefore, this Special Report is being submitted.

The lock set on the door was replaced and the door was declared operable at 1557 on 2-27-88. All Technical Specification action statements for the door were met.

8803280158 880321
PDR ADOCK 05000348
S DCD

IF22
71

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291-0400
Telephone 205 250-1835

R. P. McDonald
Senior Vice President



March 21, 1988

Docket No. 50-348

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant - Unit 1
Licensee Event Report No. LER 88-005-00

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 88-005-00 is being submitted in accordance with 10CFR50.73.

If you have any questions, please advise.

Respectfully submitted,

R. P. McDonald

RPM/JAR:dst-D-1.55

Enclosure

cc: IE, Region II

TR22
11