

Log # TXX-88101 CPRT-1096 File # 10068

William G. Counsil Executive Vice President January 18, 1988

U. S. Nuclear Regulatory Commission

Attn: Document Control Desk Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)

DOCKET NOS. 50-445 AND 50-446

CPRT RESULTS REPORTS

Gentlemen:

We transmit herewith the following SRT approved Results Reports:

ISAP VII.b.3 - Pipe Support Inspections

These reports should be placed in sequence behind the tab "QA/QC". A new binder is being provided for expansion (Volume IV). Also enclosed is a revised Table of Contents reflecting the issuance of these reports.

The files which contain supporting documentation for these Reports will be available for public inspection at the following locations:

I.d.1 QC Inspector Qualifications - Dallas or CPSES

VII.b.3 Pipe Support Inspections - CPSES Only

Anyone wishing to inspect these files should contact Ms. Debra Anderson at (214) 812-4379.

8801260507 880118 PDR ADOCK 05000445 A PDR Very truly yours,

W. G. Counsil

TLS/mlh Enclosures

c - Mr. R. D. Martia, Region IV Resident Inspectors, CPSES (3) D029 w/sinders

TABLE OF CONTENTS

COLLECTIVE SIGNIFICANCE REPORT

- Later -

COLLECTIVE EVALUATION REPORT

- Issued -

RESULTS REPORTS

Electrical

I.a.1	Heat-Shrinkable Cable Insulation Sleeves - Revision 1
I.a.2	Inspection Reports on Butt-Splices, Revision 1
I.a.3	Butt-Splice Qualification - Revision 1
I.a.4	Agreement Between Drawings and Field Terminations - Revision 2
I.a.5	NCR's on Vendor Installed Amp Terminal Lugs - Revision 1
I.b.1	Flexible Conduit to Flexible Conduit Separation - Revision 1

- I.b.2 Flexible Conduit to Cable Separation Revision 1
- I.b.3 Conduit to Cable Tray Separation Revision 1
- I.b.4 Barrier Removal Revision 1

Civil/Structural

1.6	irain C cond	luit and	Supports	- KE	evision	1
II.a	Reinforcing Revision 1	Steel in	the Rea	ctor	Cavity	

- II.b Concrete Compression Strength Revision 1
- II.c Maintenance of Air Gap Between Concrete Structures Revision 1
- II.d Seismic Design of Control Room Ceiling Elements -Revision 1
- II.e Rebar in the Fuel Handling Building Revision 1

Testing	
III.a.1	Hot Functional Testing - Revision 1
III.a.2	JTG Approval of Test Data - Revision 0
III.a.3	Technical Specification for Deferred Tests - Revision O
III.a.4	Traceability of Test Equipment - Revision 0
III.a.5	Preoperational Test Review and Approval of Results Revision 1
III.b	Conduct of the CILRT - Revision 0
III.c	Prerequisite Testing - Revision 1
III.d	Preoperational Testing - Revision 1
Mechanical	
V . a	Inspection for Certain Types of Skewed Welds in NF Supports - Revision 1 with Errata
V . b	Improper Shortening of Anchor Bolts in Steam Generator Upper Lateral Supports - Revision O
V.c	Design Consideration for Piping Systems Between Seismic Category I and Non-Seismic Category I Buildings - Revision 1
V.d	Plug Welds - Revision 1
V.e	Installation of Main Steam Pipes - Revision !
VI.a	Gap between Reactor Pressure Vessel Reflective Insulation and the Biological Shield Wall, Revision 1

Polar Crane Shimming - Revision 1

VI.b

QA/QC	
I.d.1	QC Inspector Qualifications
I.d.2	Guidelines for Administration of QC Inspector Test - Revision 1
I.d.3	Craft Personnel Training - Revision 1
VII.a.1	Material Traceability - Revision 1
VII.a.2	Nonconformance and Corrective Action System - Revision 1
VII.a.3	Document Control - Revision 1
VII.a.4	Audit Program and Auditor Qualification - Revision 1
VII.a.5	Periodic Review of QA Program - Revision 1
VII.a.6	Exit Interviews - Revision 1
VII.a.7	Housekseping and System Cleanliness - Revision 1
VII.a.8	Fuel Pool Liner Documentation - Revision 1
VII.b.1	Onsite Fabrication - Revision 1
VII.b.2	Valve Disassembly - Revision 1
VII.b.3	Pipe Support Inspections
VII.b.4	Hilti Anchor Bolt Installation - Revision 1
VII.c	Construction Reinspection/Documentation Review Plan
DSAPs	
IIIV	Civil/Structural - Train A & B Conduit and Supports - Revision 1
IIIA	Civil/Structural - Cable Trays and Supports - Revision 1
IX	Piping and Supports Discipline Specific Action Plan - Revision 1