

UNITED STATES

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

June 6, 1997

Mr. C. L. Terry TU Electric Group Vice President, Nuclear ATTN: Regulatory Affairs Department P.O. Box 1002 Glen Rose, Texas 76043

SUBJECT: NRC INSPECTION REPORT 50-445/97-06, 50-446/97-06 AND NOTICE OF VIOLATION

Dear Mr. Terry:


An NRC inspection was conducted during the periods of March 3-14, 1997, and April 28, through May 2, 1997, at your Comanche Peak Steam Electric Station, Units 1 and 2, reactor facility. The enclosed report presents the scope and results of that inspection.

The purpose of this inspection was primarily to evaluate the effectiveness of the licensed operator requalification program. It also involved substantial observations of control room performance. Overall, the licensed operator requalification training program effectively implemented a systems apply ach to training and maintained the condition of licenses.

We appreciate the support and hospitality your staff gave to the visiting inspector from the Canadian Atomic Energy Control Board, who accompanied the NRC inspectors.

We are concerned, however, about a violation of NRC requirements, which is identified in the enclosed report. The violation of NRC requirements was identified by our inspectors. The violation involved a failure to have procedures to ensure that all licensed operators that have their licenses conditioned to wear corrective lenses for the eye, always have available appropriate lenses qualified for a self-contained breathing apparatus.

The violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding the violation are described in detail in the enclosed report. The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence is already adequately addressed in the enclosed report. Therefore, you are not required to respond to this letter unless the description therein does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.





In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response to the violation (should you choose to provide a response), will be placed in the NRC Public Document Room (PDR). To the extent possible your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

lui

Arthur T. Howek-III, Director Division of Reactor Safety

Docket Nos.: 50-445; 50-446 License Nos.: NPF-87; NPF-89

Enclosures:

- 1. Notice of Violation
- 2. NRC Inspection Report
- 50-445/97-06; 50-446/97-06

cc/w enclosures: Mr. Roger D. Walker **TU Electric Regulatory Affairs Manager** P.O. Box 1002 Glen Rose, Texas 76043

Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

TU Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814

George L. Edgar, Esq. Morgan, Lewis & Bockius 1800 M. Street, NW Washington, L.C. 20036

G. R. Bynog, Program Manager/ Chief Inspector
Texas Department of Licensing & Regulation
Boiler Division
P.O. Box 12157, Capitol Station
Austin, Texas 78711

Honorable Dale McPherson County Judge P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 78756

John Howard, Director Environmental and Natural Resources Policy Office of the Governor P.O. Box 12428 Austin, Texas 78711

Steve Falley TU Electric Operator Training Supervisor P.O. Box 1002 Glen Rose, TX 76043-1147

E-Mail report to T. Boyce (THB) E-Mail report to NRR Event Tracking System (IPAS) E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD_(IE42) bcc distrib. by RIV:

Regional Administrator DRP Director Branch Chief (DRP/A) Project Engineer (DRP/A) Branch Chief (DRP/TSS) Stuart Richards, NRR/HOLB Resident Inspector (2) DRS-PSB MIS System RIV File Lean Tremper (OC/LFDCB, MS: TWFN 9E10) Laura Hurley, DRS/OB

JRS AT 96-2-0067

DOCUMENT NAME: CP706RP.TRM

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RE:OB	RIV:RE	RIV:RE		D:DRP	D:DRS
TRMeadows/Imb*	RELantz*	VLOrdaz*	JLPellet*	TPGwynn	ATHOWALI
05/27/97	05/30/97	05/30/97	05/30/97	053097	08/097

*Previously concurred

OFFICIAL RECORD COPY

.

E-Mail report to T. Boyce (THB) E-Mail report to NRR Event Tracking System (IPAS) E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IE42) bcc distrib. by RIV:

Regional Administrator DRP Director Branch Chief (DRP/A) Project Engineer (DRP/A) Branch Chief (DRP/TSS) Stuart Richards, NRR/HOLB Resident Inspector (2) DRS-PSE MIS System RIV File Leah Tremper (OC/LFDCB, MS: TWFN 9E10) Laura Hurley, DRS/OB

JRS AI 96-2-0067

DOCUMENT	NAME:	CP70	06RP.	TRM	

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:RE:OB	RIV:RE	RIV:RE	C:OB	D:DRP	D:DRS
TRMeadows/Imb*	RELantz*	VLOrdaz*	JLPellet*	TPGwyn	ATHOW ALIII
05/27/97	05/30/97	05/30/97	05/30/97	0530/97 (00/097
Previously concurre	ed	OFFICIAL F	RECORD CO	PY	0