

March 24, 1988 NRC-88-0072

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555 NRC Identification No.: TACS 65955/65956

References: 1) Fermi 2 NRC Docket No. 50-341 NRC License No. NPF-43

> 2) NRC Bulletin No. 88-01: Defects in Westinghouse Circuit Breakers

Subject: Response to NRC Bulletin No. 88-01

In response to the NRC Bulletin No. 88-01 (Reference 2) Detroit Edison Company hereby provides the information required regarding the subject circuit breakers. Fermi 2 does not utilize Westinghouse circuit breakers referenced in this bulletin. In addition, the Westinghouse switchgear, which normally use such circuit breakers, are on our Restricted Engineered Components List for "not to be used at Fermi 2".

Since the bulletin addresses component failure specific to a single manufacturer not utilized at Fermi 2, no further action is required.

If you have any questions, please contact Mr. G. S. Shukla at (313) 586-4270.

Sincerely.

Black Solin

cc: Mr. A. P. Davis

Mr. R. C. Knop

Mr. T. R. Quay

Mr. W. G. Rogers

8803300131 880324 PDR ADDCK 05000341

IE 11