


YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367

July 5, 1974



Mr. J. P. O'Reilly, Director
Directorate of Regulatory Operations, Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Abnormal Occurrence 50-29/74-3
Protective Instrumentation Setpoint Drift


Dear Mr. O'Reilly:

In accordance with Technical Specifications, Section E.2.a, the attached report of Abnormal Occurrence 50-29/74-3 is hereby submitted.

Very truly yours,

Herbert A. Autio

Herbert A. Autio
Plant Superintendent



THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

6335

8011240 117

5