

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH January, 1988

DOCKET NO. 50-412
 UNIT NAME BVPS Unit 2
 DATE March 10, 1988
 COMPLETED BY M.A. Winger
 TELEPHONE (412) 643-1825

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
1	880127	F	.1	A	3	88-02	EB	ELECON	At 0152 hours on the 27th, the Unit tripped after the 'A' 4KV bus became de-energized.
2	880127	S	118.0	B	9	N/A	CA	VESSEL	The Unit remained shutdown to perform scheduled maintenance on a leaking pressurizer manway.

¹
 F Forced
 S Scheduled

²
 Reason:
 A Equipment Failure (Explain)
 B Maintenance or Test
 C Refueling
 D Regulatory Restriction
 E Operator Training & License Examination
 F Administrative
 G Operational Error (Explain)
 H Other (Explain)

³
 Method:
 1-Manual
 2-Manual Scram
 3-Automatic Scram
 4-Continued From Previous Month
 5-Reduction
 9-Other

⁴
 Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG 0161)

⁵
 Exhibit I - Same Source

(1/77)

BB04040064 880310
 PDR ADOCK 05000334
 R PDR