

Point Beach Nuclear Plant 6610 Nuclear Rd., Two Rivers, WI 54241 (414) 755-2321

NPL 97-0363

June 19, 1997

Document Control Desk U.S. NUCLEAR REGULATORY COMMISSION Mail Station P1-137 Washington, D. C. 20555

Ladies/Gentlemen:

DOCKETS 50-266 AND 50-301
LICENSEE EVENT REPORT 97-025-00
PRESSURIZER LEVEL CONTROLLED HIGHER THAN
ASSUMED IN ACCIDENT ANALYSIS
POINT BEACH NUCLEAR FLANT, UNITS 1 AND 2

Enclosed is Licensee Event Report 97-025-00 for Point Beach Nuclear Plant, Units 1 and 2. This report is provided in accordance with 10 CFR 50.73(a)(2)(ii)(A), "Any event or condition that resulted in the nuclear power plant being in an unanalyzed condition that significantly compromised plant safety." This report describes the situation in which pressurizer level was procedurally controlled at a level greater than assumed in the Point Beach FSAR section 14.2.5 rupture of a steam pipe accident analysis during reactor shutdown.

New commitments within the report are indicated in italies.

Please contact us if you require additional information.

Sincerely,

D. F. Johnson

Manager - Regulatory Services & Licensing

IEDO!

Enclosure

cc: NRC Resident Inspector

Torgo E golden

NRC Regional Administrator

PSCW

9706260317 970619 PDR ADOCK 05000266 S PDR

