

APR 6 1988

In Reply Refer To:
Docket: 50-482/87-34

**Document Contains
SAFEGUARDS INFORMATION**

Wolf Creek Nuclear Operating Corporation
ATTN: Bart D. Withers
President and Chief Executive Officer
P.O. Box 411
Burlington, Kansas 66839

Gentlemen:

This is in response to your letters of January 28 and March 29, 1988, in response to our letter and attached Notice of Violation dated December 29, 1987, and our subsequent letter of March 21, 1988.

In your response of March 29, 1988, we find that you have adequately addressed the concerns raised by the Violation cited in Inspection Report 50-482/87-34. As discussed with your representative on March 31, 1988, our response does not provide tacit approval of your CCTV maintenance program, but recognizes your commitment to return the CCTV system to its original performance level and to maintain it there. Your maintenance program may need to be modified periodically to ensure high level performance of the system. We will review your corrective actions and the adequacy of the CCTV system in a future inspection.

Sincerely,
Original Signed By
L. J. Callan

L. J. Callan, Director
Division of Reactor Projects

cc:
Wolf Creek Nuclear Operating Corporation
ATTN: Otto Maynard, Manager
of Licensing
P.O. Box 411
Burlington, Kansas 66839

Wolf Creek Nuclear Operating Corporation
ATTN: Gary Boyer, Plant Manager
P.O. Box 411
Burlington, Kansas 66839

Kansas Corporation Commission
ATTN: Robert D. Elliott, Chief Engineer
Fourth Floor, Docking State Office Building
Topeka, Kansas 66612-1571

Kansas Radiation Control Program Director

bcc: (see next page)

RIV: *[Signature]* RPSB
RJEvetett/jt
4/4/88

C:RPBS *[Signature]*
LAYandell
4/4/88
C:DRP/A
[Signature] Chamberlain
4/4/88

D:DRP *[Signature]*
LJCallan
4/5/88

**Document Contains
SAFEGUARDS INFORMATION**

8804140086 880406
PDR ADOCK 05000482
Q DCD

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

1/1
TE 04

bcc w/copy of licensee's response w/safeguards:

RIV Security File
P. A. Starcher, RSGB/NRR
Resident Inspector
R. D. Martin, RA
R. L. Bangart, DRSS
Security Inspector
Chief, RPSB
RPSB Security File

bcc w/copy of licensee's response w/o safeguards:


✓ DMB IE-04
MIS
DRP
Lisa Shea, RM/ALF
Section Chief, DRP/A
RIV File
RSTS Operator
RPSB
Myron Karman, zLD, MNDB
DRS
R. E. Hall, DRSS
Project Engineer, DRP/A
B. DeFayette, RIII
Callaway, RIII
P. C'Conner, NRR Project Inspector

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

WOLF CREEK

NUCLEAR OPERATING CORPORATION

John A. Bailey
Vice President
Engineering and Technical Services



March 29, 1988

ET 88-0047

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

COPY NO LIC-3

Subject: Docket No. 50-482: Supplemental Response to
Inspection Report 50-482/87-34

Gentlemen:

The attached supplemental response to the violation included in Inspection Report 50-482/87-34 is being provided to document additional actions Wolf Creek Nuclear Operating Corporation is taking to address the Security related concerns identified in the Inspection Report. As a result of recent discussions between Mr. Jerry Everett of your staff and Mr. Otto Maynard of my staff, Wolf Creek believes the issues have been clarified and that the attached supplemental response addresses these issues.

If you have any further questions concerning this matter please contact Mr. Otto Maynard of my staff.

Very truly yours,

John A. Bailey
Vice President
Engineering and Technical Services

BDW/jad

Attachment

cc: B. L. Bartlett (NRC), w/o
J. Everett (NRC), w/a
R. D. Martin (NRC), w/a
P. W. O'Connor (NRC), 2 w/o

WHEN SEPARATED FROM
ENCLOSURES, HANDLE
THIS DOCUMENT AS
DECONTROLLED.

SPECIAL DELIVERY

RECEIVED

APR 1 1988

~~8804060431 LP~~