

**Northeast
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

JUN 30 1997

Docket No. 50-336
B16523

Re: 10 CFR 50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 97-020-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on April 23, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i). This LER supplement provides an update on the analyses and investigation for this event.


The following are NNECO's commitments made within this letter.

- B16523-01: The appropriate surveillance procedure shall be revised prior to entry into Mode 6 from the current outage to ensure that the power operated valves for all credited flowpaths are properly tested.
- B16523-02: Technical Specification surveillance procedures will be reviewed to ensure compliance with Technical Specifications surveillance requirements as part of Millstone Unit 2 Operational Readiness Plan (Reference NOV 336/96-08-07, NNECO Commitment No. B16076-2).

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

9707070391 970630
PDR ADOCK 05000336
S PDR



J. A. Price
Director - Millstone Unit No. 2

11
1022

cc: see page 2



Attachment: LER 97-020-01

cc: H. J. Miller, Region I Administrator
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
W. D. Travers, PhD, Director, Special Projects Office
P. F. McKee, Deputy Director of Licensing, Special Projects Office
W. D. Lanning, Deputy Director of Inspections, Special Projects Office