NRC Form 591			U.S. NUCLEAR REGULATORY COMMISSION
12-81) 10 CFR 2.201 SAFETY INSPECTION			
	GALETTI		
1. LICENSEE U.S. Deportment of the I. Bureau of Indian Affairs Federal Courthouse Muskogee, Oklahoma 7 3. DOCKET NUMBER(S)	ntenion , Branch of Roads 14401	2. REGIONAL OFFICE U.S. NRC, G1! Ryan 1 Arlington,	Region IV Plaza, Suite 1000 Texas 76011
30-08789	35-15239	-01	Jan. 22, 1988
Licensee: The inspection was an examination of the activities Regulatory Commission's (NRC) rules and regulation and representative records, interviews, with personn 1. Within the scope of this inspection, no violat 2. The inspector also verified the steps you have those actions at this time. 3. During this inspection certain of your activitient THIS IS A NOTICE OF VIOLATION which A	ns and the conditions of you el, and observations by the ions were observed. It taken to correct the violat ies, as checked below, were is required to be posted in	ur license. The inspection inspector. The findings at ions identified during the in violation of NRC requi accordance with 10 CFR 1	consisted of selective examinations of procedures s a result of this inspection are as follows: last inspection. We have no further questions on rements.
			of sealed sources were not performed at the proper
frequencies. 10 CFR			ndition Number
D. Records of 10 CFR		or License Condition Num	were not properly maintained.
E. Documents were not properly posted or o	therwise made available. 1	0 CFR 19.11.	
F. Reports or notifications of			ber were not made in accordance
XH. Shipping papers we radioactive materials	contrary	ed when tr to License	ansporting licensed Condition 16.
ВВ02020219 ВЕ REG4 L I C30 REG4 L I C30 35-15239-01	90122 PDR		1001 1001
I hereby state that within 30 days the actions described in the NRC.			