

NOTICE OF VIOLATION

Commonwealth Edison Company
LaSalle Units 1 and 2

Docket No. 50-373
Docket No. 50-374

As a result of the inspection conducted on March 14-18, 1988, and in accordance with 10 CFR Part 2, Appendix C - General Statement of Policy and Procedure for NRC Enforcement Actions (1987), the following violation was identified:

10 CFR 50, Appendix B, Criterion XVI, as implemented by the Commonwealth Edison Quality Assurance Program, as described in Section 16 of Topical Report CE-1, requires that conditions adverse to quality be promptly identified and corrected.

Contrary to the above, as of March 18, 1988, there were 64 Discrepancy Records open greater than 90 days, 27 of which were identified prior to 1987, including problems with instruments out of calibration and installation of nonsafety-related parts in a safety-related system.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

4-8-88
Dated

F. J. Jablon
J. J. Harrison, Chief
Engineering Branch