APPENDIX B

U.S. NUCLEAR REGULATORY COMMISSION REGION IV

NRC Inspection Report: 50-498/87-72

Operating License: NPF-71

50-499/87-72

Construction Permit: CPPR-129

Dockets: 50-498

50-499

Licensee: Houston Lighting & Power Company (HL&P)

P.O. Box 1700

Houston, Texas 77001

Facility Name: South Texas Project (STP)

Inspection At: Bay City, Texas

Inspection Conducted: November 16-20, 1987

Inspector:

hysical Security Inspector

Radiological Protection and Safeguards Branch

1-21-88 Date

Approved:

Yangell, Chief, Radiological Protection

and Sareguards Branch

Inspection Summary

Inspection Conducted November 16-20, 1987 (Report 50-498/87-72)

Areas Inspected: Routine, unannounced inspection of the licensee's locks, keys, and combinations; physical barriers for both protected and vital areas; detection aids - vital areas; and security system power supply.

Results: Within the areas inspected, two violations were identified (locks, keys, and combinations, paragraph 3; vital area - detection aids, paragraph 4).

Inspection Conducted November 16-20, 1987 (Report 50-499/87-72)

Areas Inspected: No inspection of Unit 2 was conducted.

Results: Not applicable.

8802020303 880125 ADDCK 05000498 PDR

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION. UPON SEPARATION THIS PAGE IS DECONTROLLED.