



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

January 27, 1988

FILE: B09-13510C  
SERIAL: BSEP/88-0068


U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2  
DOCKET NO. 50-325 AND 50-324  
LICENSE NO. DPR-71 AND DPR-62  
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.7.2 AND  
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-87-003)

Gentlemen:

During power operation of Units 1 and 2, at 0820 hours on December 17, 1987, a Limiting Condition for Operation (LCO) was established to permit the removal from service of the fire suppression sprinkler header in the units' common Radiological Waste Control System waste drumming room. This was done to allow replacement of the header flow switch 2-FP-FS-4059. During installation of a replacement switch, the switch housing was inadvertently cracked which prevented use of the device. Due to unavailability of an additional switch in the plant supply system, the 14-day time frame of the subject LCO was exceeded on December 28, 1987. Following the acquisition and installation of a replacement switch, the sprinkler header will be returned to service and the subject LCO will be cancelled.

Very truly yours,

  
C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

MJP/hag

Enclosure

cc: Dr. J. N. Grace  
Mr. E. D. Sylvester  
BSEP NRC Resident Office

8802020338 880127  
PDR ADOCK 05000324  
S PDR

IE22  
1/0