

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-373

Docket No. 50-374

As a result of the inspection conducted on December 1, 1987 through January 5, 1988, and in accordance with 10 CFR Part 2, Appendix C - General Statement of Policy and Procedure for NRC Enforcement Actions (1987), the following violation was identified:


10 CFR Part 50, Appendix B, Criterion XVI, as implemented by the Commonwealth Edison Company Topical Report CE-1-A requires that a corrective action system be established to assure that such items as deviations, defective equipment and deficiencies which are adverse to quality are promptly identified and corrected.

Contrary to the above, the licensee did not establish measures to adequately control the use of out of calibration measuring equipment and evaluate the effects of flowmeters Nos. 614 and 622 on operating equipment during the period from the previous calibration to the subsequent calibration date.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated \_\_\_\_\_

  
\_\_\_\_\_  
G. C. Wright, Chief  
Operations Branch