

APPENDIX A

University of Kansas
Docket No. 50-148

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted October 4-6, 1978, it appears that certain of your activities were not conducted in full compliance with your Reactor License or NRC regulations as indicated below:

Technical Specification J.8 requires in part that, ". . . All activities listed in Section J.3 above shall be performed in accordance with approved written procedures."

Technical Specification J.3 requires in part that, "The Nuclear Reactor Committee shall review and approve written procedures for: . . . C. Fuel loading or unloading"

Contrary to the above, fuel element number 412 was the first element removed from the core instead of fuel element number 413 as required by the procedure for "Complete or Partial Unloading and Subsequent Reloading of Core." Removal of number 413 was required to create core configuration number 1.

This is an infraction.

7812060326