FEB 0 4 1988

41/2

Docket Nos. 50-413, 50-414 License Nos. NPF-35, NPF-52

Dyke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-413/88-02 AND 50-414/88-02

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by R. W. Newsome on January 11-15, 1988. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

8802090060 880204 PDR ADOCK 05000413 Q PDR Jerome J. Blake

Alan R. Herdt, Chief Engineering Branch Division of Reactor Safety

Enclosure: NRC Inspection Report

cc w/encl: J. W. Hampton, Station Manager Senior Resident Inspector - McGuire

bcc w/encl: (See page 2)

bcc w/encl:

K. N. Jabbour, NRR

MRC Resident Inspector

DRS Technical Assistant

Document Control Desk

State of South Carolina

RII 7NJ RNewsome:1b 01/21/33

01/3/88

