



Log # TXX-7129  
File # 10110  
903.10  
Ref. # 10CFR50.55(e)

William G. Council  
Executive Vice President

December 28, 1987

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NOS. 50-445 AND 50-446  
NOZZLE LOAD INTERFACES  
SDAR: CP-87-122 (INTERIM REPORT)

Gentlemen:

On November 25, 1987, we verbally notified your Mr. R. F. Warnick of a deficiency involving nozzle load stresses (for various nozzles) which may fail to meet FSAR limits. This condition was discovered during seismic equipment qualification review activities and is potentially reportable under the provisions of 10CFR50.55(e).

Further evaluation is required to assess the possible impact of these discrepancies.

Our next report on this issue will be submitted by March 9, 1988.

Very truly yours,  
*W. G. Council*  
W. G. Council

By: *J. S. Marshall*  
J. S. Marshall  
Supervisor, Generic Licensing

CBC/mlh

c - Mr. R. D. Martin, Region IV  
Resident Inspectors, CPSES (3)

8801040456 871228  
PDR ADOCK 05000445  
S DCD

IE27  
1/0