

Robert W. Boyce Plant Manager Limerick Generating Station

PECO Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 610 718 2000

10CFR50.73

1/1 Ierz

July 09, 1997 Docket No. 50-353 License No. NPF-85

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Subject: Licensee Event Report

Limerick Generating Station - Unit 2

This LER reports a Primary Containment and Reactor Vessel Isolation Control System actuation, an Engineered Safety Feature, resulting in automatic closure of the Reactor Core Isolation Cooling (RCIC) system steam supply line inboard and outboard Primary Containment Isolation Valves (PCIVs). The PCIV isolations were caused by personnel error during restoration of the RCIC system.

Reference:

Docket No. 50-353

Report Number:

2-97-006

Revision Number:

00

Event Date:

June 11, 1997

Report Date:

July 09, 1997

Facility:

Limerick Generating Station

PO Box 2300, Sanatoga, PA

19464-2300

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv).

Very truly yours,

A. Hutton for R. W. Boyce

DMS/cah

cc: H. J. Miller, Administrator Region I, USNRC

N. S. Perry, USNRC Senior Resident Inspector, LGS

9707160019 970709 PDR ADOCK 05000353 S PDR

Octobro (Control of Control of Co

150013