

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station Northeast Nuclear Energy Company P.O. Box 128 Waterford, CT 06385-0128 (860) 447-1791 Fax (860) 444-4277

The Northeast Utilities System

July 14, 1997

Docket No. 50-336 B16599

Re: 10 CFR 50.73(a)(2)(ii) 10 CFR 50.73(a)(2)(v)

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

This letter forwards Licensee Event Report (LER) 97-023-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on June 12, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(ii) and 10 CFR 50.73(a)(2)(v).

The following are NNECO's commitments made within this letter.

B16599-01:

The affected accident analyses will be evaluated with conservative HPSI delivery rates prior to entering Mode 4 from the current outage to determine if accident acceptance criteria are met.

B16599-02:

Investigation of this event is continuing to ensure appropriate corrective actions are identified. A supplement to this LER will be submitted by October 1, 1997 to provide additional information identified as a result of this investigation.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

9707160089 970714 PDR ADOCK 05000336 S PDR

cc: see page 2

J. A. Hrice Director - Millstone Unit No. 2.

Manager A

U. S. Nuclear Regulatory Commission B16599/Page 2

Attachment: LER 97-023-00

cc: H. J. Miller, Region I Administrator

D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2

D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2

W. D. Travers, PhD, Director, Special Projects Office

P. F. McKee, Deputy Director of Licensing, Special Projects Office

W. D. Lanning, Deputy Director of Inspections, Special Projects Office