

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

January 4, 1988


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 2
Docket No. 50-414
Special Report Concerning a Diesel Generator 2B
Invalid Failures on January 15, 1988

Gentlemen:

Please be advised that submittal of a Special Report concerning three January 15, 1988 invalid failures of Unit 2 Diesel Generator 2B will be delayed until February 29, 1988. Submittal of this report was originally scheduled for January 12, 1988. The extension is required to allow Duke Power personnel in charge of the investigation sufficient time to review the failures. This event is reportable pursuant to Technical Specification 3/4.8.1.1.3 and 6.9.2.

Very truly yours,



Hal B. Tucker

JGT/1324/sbn

xc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

8802110138 880104
PDR ADOCK 05000414
S PDR

IE22
1/0