U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-456/94010(DRSS): 50-457/94010(DRSS)

Dockets No. 50-456: 50-457

Licenses No. NPF-72: NPF-77

Licensee: Commonwealth Edison Company

Opus West III 1400 Opus Place

Downers Grove, IL 60515

Facility Name: Braidwood Nuclear Station, Units 1 and 2

Inspection Dates: March 24-May 24, 1994

Type of Inspection: Unannounced, Reactive, Fitness For Duty

Date of Previous Physical Security Inspection: January 3-25, 1994

Inspectori and Celed

Plant Protection Analyst

Approved By:

James R. Creed, Chief

Safeguards and IR Section

Inspection Summary

Inspection on March 24-May 24, 1994 (Reports No. 50-456/94010(DRSS); 50-457/94010(DRSS))

Areas Inspected: Reactive, unannounced physical security inspection involving concerns relating to Fitness For Duty.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined. A concern regarding an individual reporting to work in an intoxicated condition, could not be substantiated. A concern regarding the failure of two supervisors to take appropriate action when informed of a FFD concern, was partially substantiated, in that one supervisor did not take appropriate initial action. Weaknesses were found with FFD procedures, regarding clarity and detail. No response is necessary. (Refer to Section 3.)

> INCLOSURE CONTIN 10CFR2.790 TION THIS S DESIGTROLLED