

DMB COPY

FEB 16 1988

30-19478

Envirodyne Engineers, Inc.
ATTN: Paul Clifford, Ph.D.
Manager
12161 Lackland Rd.
St. Louis, MO 63146

License No. 24-17152-02

Gentlemen:

This refers to the routine safety inspection conducted by Ms. T. L. Simmons of this office on January 28, 1988 of activities authorized by NRC Byproduct Material License No. 24-17152-02 and to the discussion of our findings with Mr. J. Coniglio at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice (Order) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski
Nuclear Materials Safety
Section 2

Enclosure: Notice of
Violation

cc w/enclosure:
DCD/DCB (RIDS)
John Coniglio

RIII

Simmons/md

RIII

Sreniawski

2/14/88

8802190205 880216

REG3 LIC30

ncn

IE07

11