

*official*

FEB 16 1988

Docket Nos. 50-321, 50-366  
License Nos. DPR-57, NPF-5

Georgia Power Company  
ATTN: Mr. James P. O'Reilly  
Senior Vice President-  
Nuclear Operations  
P. O. Box 4545  
Atlanta, GA 30302

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-321/88-04 AND 50-366/88-04

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by C. H. Bassett on January 25-29, 1988. The inspection included a review of activities authorized for your Hatch facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

ORIGINAL SIGNED BY  
DOUGLAS M. COLLINS

Douglas M. Collins, Chief  
Emergency Preparedness and  
Radiological Protection Branch  
Division of Radiation Safety  
and Safeguards

Enclosure:  
Inspection Report

cc w/encl: (See page 2)

8802250495 880216  
PDR ADOCK 05000321  
Q PDR

*11*  
*IEC*

cc w/encl:  
J. T. Beckham, Vice President, Plant Hatch  
H. C. Nix, Plant Manager  
O. M. Fraser, Site Quality Assurance (QA)  
Supervisor  
L. Gucwa, Manager, Nuclear Safety  
and Licensing

bcc w/encl:  
NRC Resident Inspector  
DRS Technical Assistant  
Hugh S. Jordan, Executive Secretary  
Document Control Desk  
State of Georgia

RII  
*for PW*  
CBassett  
2/10/88

RII  
*for PW*  
Chosey  
2/10/88

RII  
*MS*  
MSinkule  
2/10/88