

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant  
Post Office Box 2000  
Soddy-Daisy, Tennessee 37379

March 10, 1988

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO.  
50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT  
SQRO-50-327/87037 REVISION 1

The enclosed revised licensee event report provides additional information relating to the corrective action taken by TVA to ensure that engineered safety feature area/room coolers have sufficient cooling capacity. This report also includes additional information relating to an Auxiliary Building backdraft damper. This event was originally reported in accordance with 10 CFR 50.73, paragraph a.2.ii, on August 27, 1987.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
S. J. Smith  
Plant Manager

Enclosure  
cc (Enclosure):

J. Nelson Grace, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, Sequoyah Nuclear Plant

8803180276 880310  
PDR ADOCK 05000327  
S PDR

LE22  
11