



Log # TXX-88374  
File # 10110  
903.11  
Ref. # 10CFR50.55(e)

March 31, 1988

William G. Council  
*Executive Vice President*

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NOS. 50-445 AND 50-446  
UNQUALIFIED LIMITORQUE ACTUATORS  
SDAR: CP-87-132 (FINAL REPORT)

Gentlemen:

On January 5, 1988, we notified you by our letter, logged TXX-88027, of a deficiency involving unqualified limitorque actuators which we deemed reportable under the provisions of 10CFR50.55(e). Our latest report was logged TXX-88337 dated March 29, 1988. This report is submitted to provide the corrective action completion schedule.

As indicated in TXX-88027, all Class 1E limitorque actuators will be examined and corrected where necessary under Field Verification Method TE-FVM-EQ-047.

Unit 1 corrective actions are currently scheduled for completion by September 1, 1988. The corresponding Unit 2 corrective actions will be completed prior to Unit 2 hot function testing.

Very truly yours,

*W.G. Council*  
W. G. Council

By: *D.R. Woodlan*  
D. R. Woodlan  
Docket Licensing Manager

VIP/grr

c-Mr. R. D. Martin, Region IV  
Resident Inspectors, CPSES (3)

8804050038 880331  
PDR ADOCK 05000445  
S DCD

JE27  
1/0