

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO.

50-266

UNIT NAME

Point Beach Unit 1

DATE

June 17, 1988

REPORT MONTH MAY 1988

COMPLETED BY

C. W. Krause

TELEPHONE

414/221-2001

| No. | Date | Type ¹ | Duration (Hours) | Reason ² | Method of Shutting Down Reactor ³ | Licensee Event Report No. | System Code ⁴ | Component Code ⁵ | Cause & Corrective Action To Prevent recurrence |
|-----|--------|-------------------|---------------------|---------------------|--|------------------------------|-----------------------------|--------------------------------|--|
| 1 | 880409 | S | 470 | C | 4 | N/A | ZZ | ZZZZZZ | Shutdown for annual refueling and maintenance |
| 2 | 880521 | S | .6 | B | 6 | N/A | ZZ | ZZZZZZ | Generator taken off line to complete post-outage turbine overspeed tests |

¹F: Forced
S: Scheduled

²Reason:
A - Equipment Failure (explain)
B - Maintenance or Test
C - Refueling
D - Regulatory Restriction
E - Operator Training &
Licensing Exam
F - Administrative
G - Operational Error (explain)
H - Other (explain)

³Method:
1 - Manual
2 - Manual Scram
3 - Automatic Scram
4 - Continuation of
Previous Shutdown
5 - Reduced Load
6 - Other (explain)

⁴Exhibit G-Instructions
for preparation of
data entry sheets
LER file (NUREG-0161)

⁵Exhibit I-Same Source