

APR 14 1988

DCS

Docket No. 50-334

Duquesne Light Company
ATTN: Mr. J. D. Sieber
Vice President
Nuclear
Post Office Box 4
Shippingport, Pennsylvania 15077

Gentlemen:

Subject: Inspection Report 50-334/88-02

This refers to the special inspection conducted by Mr. P. Bissett and Mr. N. Dudley of this office on February 1-5, 1988 at the Beaver Valley Unit 1 facility of activities authorized by NRC License No. DPR-66 and to the discussions of our findings held by Mr. Dudley with Mr. K. Grada of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed. However, one activity appears to be a deviation from a Duquesne Light Company commitment to adhere to the Procedures Generation Package in developing your Emergency Operating Procedures. Numerous inconsistencies with the Procedures Generation Package were identified in procedural steps of the Emergency Operating Procedures. Many of these inconsistencies resulted in the Emergency Operating Procedures not clearly stating what actions were required of the operators. You are requested to respond to this letter. In preparing your response you should follow the instructions contained in Appendix A.

The response requested by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us in this matter is appreciated.

Sincerely,

ROBERT M. GALLO

Robert M. Gallo, Chief
Operations Branch
Division of Reactor Safety

OFFICIAL RECORD COPY

IR BV1 88-02 - 0001.0.0
04/04/88

8804250310 880414
PDR ADOCK 05000334
Q DCD

11
1001

Enclosures:

1. Appendix A, Notice of Deviation
2. NRC Region I Inspection Report Number 50-334/88-02

cc w/encls:

H. M. Siegel, Manager, Nuclear Engineering Department
C. E. Ewing, QA Manager
W. S. Lacey, Plant Manager
R. Druga, Manager, Technical Services
R. Martin, Manager, Regulatory Affairs
J. Crockett, Senior Manager of Nuclear Operations
N. R. Tonet, Manager, Nuclear Engineering & Construction Unit
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Pennsylvania

bcc w/encl:

Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
Section Chief, DRP
J. Beall, SRI
P. Tam, LPM, NRR
Robert J. Bores, DRSS

RI:DRS
Dudley/ja
3/10/88

RI:DRS
Bissett
3/17/88

RI:DRS
Eselgroth
3/17/88

RI:DRS
Gallo
4/14/88