



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

Report Nos.: 50-259/88-20, 50-260/88-20, and 50-296/88-20

Licensee: Tennessee Valley Authority
6N 38A Lookout Place
1101 Market Street
Chattanooga, TN 37402-2801

Docket Nos.: 50-259, 50-260 and 50-296 License Nos.: DPR-33, DPR-52,
and DPR-68

Facility Name: Browns Ferry 1, 2, and 3

Inspection Conducted: June 27-July 1, 1988

Inspector: J. D. Ennis Physical Security Inspector 7/29/88
Date Signed

Approved by: William J. Tolin for 7/29/88
Date Signed
D. R. McGuire, Chief
Physical Security Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

SUMMARY

Scope: This routine, unannounced inspection was conducted in the areas of Management Effectiveness - Security Program; Security Organization; Security Program Audit; Locks, Keys, and Combinations; Physical Barriers - Vital Areas; Security System Power Supply; and Detection Aids - Protected Area. Based on a licensee letter dated June 16, 1988, the NRC agreed that the following security items were restart issues:

1. Relocation of Protected Area fence
2. Reactor Building turnstiles
3. Alarm Assessment Capability

Results: No violations of regulatory requirements were identified.

BB0B150117 BB0B01
PDR ADOCK 05000259
Q PNU

Document transmitted herewith
contains sensitive unclassified
information. When separated from
reflexes, this document is decontrolled.

SAFEGUARDS INFORMATION