



**Commonwealth Edison**  
 Braidwood Nuclear Power Station  
 Route #1, Box 84  
 Braceville, Illinois 60407  
 Telephone 815/458-2801

April 22, 1988

Mr. Thomas E. Murley, Director  
 Office of Nuclear Reactor Regulation  
 U.S. Nuclear Regulatory Commission  
 Washington, DC 20555

Subject: Braidwood Unit 1 and 2  
 Limitorque Operator Lubrication  
NRC Docket Nos. 50-456 and 50-457

Reference: (a) L. O. DelGeorge letter to T. E. Murley,  
 dated April 21, 1988  
 (b) L. O. DelGeorge letter to T. E. Murley,  
 dated April 4, 1988  
 (c) S. C. Hunsader letter to T. E. Murley,  
 dated April 22, 1988

Dear Mr. Murley:

Reference (a) provided supplemental information in response to an April 20, 1988 teleconference to discuss reference (b). Reference (c) provided Commonwealth Edison's understanding of proposed qualification testing of grease samples from four valves. In paragraph 4 of Reference c a Mode 2 schedule was identified for Braidwood Unit 2. This is an error. The April 23, 1988 Mode 2 date is actually for Braidwood Unit 1.

We regret any inconvenience this may have caused. Should you have any questions, call S. C. Hunsader of our Corporate Nuclear Licensing Office.

Very truly yours,

R. E. Querio  
 Station Manager  
 Braidwood Nuclear Station

REQ/PLB/jes  
 (6984z)

cc: S. Sands (NRR)  
 W. Forney (RIII)  
 BWD Resident Inspector  
 S. C. Hunsader

Acc  
 1/0