

040wm060110E

Wm-60



Department of Energy
Albuquerque Operations Office
P.O. Box 5400
Albuquerque, New Mexico 87115

RETURN ORIGINAL TO PDR, HQ.

JAN 3 1988,

Edward F. Hawkins
Chief
Licensing Branch 1
Uranium Recovery Field Office
Nuclear Regulatory Commission, Region IV
P.O. Box 24325
Denver, CO 80225

Dear Mr. Hawkins:

Enclosed for your review and concurrence are two copies of the Riverton Remedial Action Inspection Plan (RAIP). In accordance with the DOE/NRC Memorandum of Understanding, you are requested to provide your review and approval of the Riverton RAIP within 21 days of the receipt of this letter.

Sincerely,

Mark L. Matthews
Technical Support Group Leader
Uranium Mill Tailings Remedial Action

Enclosures (2)

W/O Encl

DESIGNATED ORIGINAL

Certified By Manly C. Hood

FEE NOT REQUIRED

Info only

8804280454 880108
PDR WASTE
WM-60 PDR

88-0279

88-0279