Digital Equipment Corporation 353 South Street Shrewsbury, Massachusetts 01545-4112 617.841.3111

June 9, 1988

## digital

Marlene Taylor U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Dear Ms. Taylor;

Pursuant to our telephone conversation on Tuesday, June 7, concerning the February 16, 1988 letter reporting the loss of seven (7) NRD Nuclecel Model P-2021 Air Line Ionizers (Serial #'s: 5630, 5639, 5642, 5643, 5644, 5647, 5650), I submit the following:

 Three (3) of the devices were subsequently located. These devices (Serial #'s 5639, 5644, 5650) were returned to the lessor, Omega Specialty Instrument Co., of North Chelmsford, MA.

Of the remaining devices, one (1) is known to have been inadvertently disposed of as solid hazardous waste and three (3) are still unaccounted for. It is very likely these devices were also disposed of in the same manner.

2. Since this incident we have tightened control of these devices. Each device at the facility has been assigned an internal control number that identifies serial number, location, and date of installation. Only authorized personnel are allowed to remove or install these devices. Devices that are removed from service will be immediately returned to the lessor. Also, all personnel working in areas where these devices are installed have been re-trained as to proper use and handling.

Please feel free to call should you have any questions or require futher information.

Sincerely,

John D. Kemp' Industrial Hygienist 1889 TON 13 BN S. PP.

8808160309 880809 REG1 QA999 EMVDIGE 99990001 PDC

CONVERSATION RECORD	)	4: 15	PA DATE	17/88	
TYPE				ROUTING	
□ VISIT □ CON	IFERENCE	E TELEP	HONE INCOMING	NAME/SYMBOL	INT
	ANIZATION (Office, de	ept., bureau,	TELEPHONE NO.	-	-
ITH YOU gold temp etc.)	gital Equi		617-841	-	
UBJECT 10 10	1 0 0	7	3117 / 400		
called for Les Boises	rault re	: miss	ing NRD		
UMMARY Discussed with The	Kemp I	the le	the we	receive	d
documenting the missing	g derice	s. In	formed	Lim H	lat
we would need another					
eappered, the actions &					
Hose they ould not for					
to them and the correct			10	1 0	200
prevent this from has			Contract of the contract of th	,	1361 134
that since then they have					
determined that one was					
Hozardous Waste drum +					
to the 3 M devices, In				. v	
not had 3 M derice, at	least not	in Y	he past	year +a.	lay
Osked him to check to were were used and	ack reco	ids 4	see if	3 M deric	es
were cere used and	if there a	ue an	y desicr	eparce	ex.
Me Leven will by Literia	a repor	T			
ACTION REQUIRED	7-7				
NAME OF PERSON DOCUMENTING CONVERSATION S	SIGNATURE		DATE		
	20 0	Taylo		6/7/88	
ACTION TAKEN		1		1	
SIGNATURE	TITLE		DATE		
50271-101 * USGPO 1986-491-248/40923 CON	VERSATION REC	ORD		OPTIONAL FORM 27 DEPARTMENT OF D	

CONVERSATION RE	CORD		6-7-88	
YPE WIEIT	CONFEDENCE	TELEPHONE	BOUTING	
□ VISIT	CONFERENCE	₩ IN	COMING NAME/SYMBOL IN	NT
ocation of Visit/Conference:	ODCANIZATION (Office		TGOING	
AME OF PERSON(S) CONTACTED OR IN CONTACT	OPGANIZATION (Office,	0 617-	841-	
Frederick Parker	Higital Eguy	o. Corp 311		
Molification of l	V			
Jafarmed Me Sa	ike Hat	we would	ned a le	tter
locumenting He ac				
situation surrounder	of the disapp	rearrances,	and their co	2-
ructive actives also	informed	The Yarke	e that I talk	red
to the inspector was	lo was at	is site (	Relchat) an	d
found out Hat the	was also	a groblem	with some	31
derices that they had	. according	to the prop	ector's records	H
licensee could have a	gurry			
account for 73. The				
to check on the where	abouts of t	le other de	reces and not	fi
the NRC. Informed				
should be addressed	I can the U	the . M	Jaiker stalled	/
that he would not	be the one	to handle &	his that The.	
Briserault of the E	vironent	I Health	+ Salety The	Total States
would hardle this.				
- Call Leo Boisenau	11 to clarify			
NAME OF PERSON DOCUMENTING CONVERSATION	Mailene	I Taylor	6-7-88	
ACTION TAKEN		0 0		
SIGNATURE	TITLE		DATE	
50271-101 * U.S.Q.F.O. 1986 - 491-248/40023	CONVERSATION RE	CORD	OPTIONAL FORM 271 (L	2-76)