

JUL 25 1988

DMB COPY

30-14669
18532

Overhoff Technology Corporation
ATTN: Mario Overhoff, Ph.D.
President
Post Office Box 182
1160 Route 50
Milford, OH 45150

License No. 34-18214-01
License No. 34-18214-02E

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. L. Lynch of this office on July 12, 1988, of activities authorized by NRC Byproduct Material Licenses No. 34-18214-01 and No. 34-18214-02E and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.


In addition to the above areas, the inspector examined actions described in your letter dated December 5, 1983, regarding apparent violations found during our July 1983 inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities under License No. 34-18214-01 appeared to be in violation of NRC requirements, as specified in the enclosed appendix and a written response is required. No violations were identified for License No. 34-18214-02E.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

8808160407 8/0725
REG3 LIC30
34-18214-01 PNU

Enclosure: Notice of Violation

cc w/enclosure
DCD/DCB (RIDS)

RIII


Lynch/mb

RII


Wiedeman

7/25/88

IE07
11