

NOTICE OF VIOLATION

Consumers Power Company

Docket No. 50-255

As a result of the inspection conducted on January 13-21, 1986, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the following violation was identified:

10 CFR 50.55a(g) requires that inservice testing of pumps be performed in accordance with Subsection IWP of Section XI of the ASME Boiler and Pressure Vessel Code.


Contrary to the above, the licensee failed to establish pump vibration reference values and corresponding alert and action levels per the ASME Code requirements defined in Paragraph IWV-3111 and Table IWP-3100-2 of Subsection IWP (1977 Edition of the ASME Code).

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

FEB 6 1986

Dated _____


Luis A. Reyes, Chief
Operations Branch

8602110159 B60206
PDR ADOCK 05000255 PDR
Q